S E R V I C E N O T E

SUPERSEDES: NONE

E5900A #300 Emulation Probe Target Interface Modules)

Serial Numbers: 0000A00000 / 9999Z99999

Possible incompatibility between the E3459-66501 and E3459-66502 Target Interface modules on some target systems.

Duplicate Service Notes:

E3459A-01, E5900A#300-01 E5901A#300-01 E5902A#300-01 E9495A#300-01

To Be Performed By: Agilent-Qualified Personnel and/or Customer

Parts Required:

| P/N | Description | Quantity |
|-------------|-------------------------|----------|
| E3459-66503 | Target Interface Module | 1ea |
| E8130-66513 | Target Adapter Board | 1ea |

Continued

DATE: June 2000

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | | |
|------------------------------|---|--|--|
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | ☐ IMMEDIATELY☐ ON SPECIFIED FAILURE☐ AGREEABLE TIME | STANDARDS: LABOR 0.5 Hours | |
| LOCATION CATEGORY: | ■ CUSTOMER INSTALLABLE □ ON-SITE □ SERVICE CENTER | SERVICE ☐ RETURN USED ☐ RETURN PARTS: ☐ SCRAP☐ SEE TEXT ☐ SEE TEXT | |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | AGILENT RESPONSIBLE UNTIL: July 2002 | |
| AUTHOR: DM | ENTITY: 0800 | ADDITIONAL INFORMATION: | |

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Situation:

The original Target Interface Module P/N E3459-66501 would not support 5-volt target systems. The P/N E3459-66502 Target Interface Module was designed for both 3.3-volt and 5-volt target systems. However, due to differences in clock signal loading of some target systems by the P/N E3459-66502 Target Interface Module, excessive clock signal noise was generated. This excessive noise caused either the target system or the emulation probe to fail to operate.

Solution / Action:

A new Target Interface Module P/N E3459-66503 was designed for a newer probe model and for compatibility with the Trace Port Analyzer. However, the connectors for TI, VLSI, and ARM high-density connectors were eliminated. Only the ARM 20-pin connector for the probe remains.

If a customer has an P/N E3459-66501 Target Interface Module and needs 5-volt support or, if the customer has problems with the P/N E3459-66502 Target Interface Module replace it with the the new Target Interface Module, P/N E3459-66503. Also provide the customer with an E8130-66513 Target Adapter Board for the additional connector capability.