E6601A-01 <u>S E R V I C E N O T E</u>

Supersedes: None

E6601A Wireless Communications Test Set

Serial Numbers: US0000000/US99999999, MY0000000/MY46160000

Recover On-Failure (ROF) Program for CISPR 11 radiated emissions test failure.

To Be Performed By: Agilent-Qualified Personnel

Parts Required: P/N	Description	Qty.
E6601-00129	Conductive Washer	2

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
MODIFICATION RECOMMENDED				
ACTION CATEGORY: :	[]] IMMEDIATELY X ON SPECIFIED FAILURE []] AGREEABLE TIME	STANDARDS LABOR: 0.20 Hours		
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER	SERVICE [[]] RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT	USED [[]] RETURN PARTS: X SCRAP [[]] SEE TEXT	
AVAILABILITY:	PRODUCTS SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: January 2010		
AUTHOR: GC		PRODUCT LINE: 13		
ADDITIONAL INFORMATION: Perform this repair on all instruments returned to Agilent Service Centers.				

© AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A.



Situation:

CISPR 11 radiated emissions test failure due to insufficient grounding on the rear panel Audio In and Audio Out connections.

Solution/Action:

Rear panel connections Audio In and Audio Out require additional grounding. This is accomplished by inserting a conductive washer between the rear panel cover and the audio connectors on the mother board. Figures 1 and 2 show the location of the parts to be installed.

Process Steps:

- 1. If the instrument is turned on, shut the instrument down via the front panel on/off button and unplug the line cord from the instrument.
- 2. Attach an electrostatic discharge strap to the instrument and take necessary electrostatic discharge precautions.
- 3. Go to Figure 1 and follow the process steps:



Next steps



11. After the conductive washers have been installed and the instrument rear panel cover has been reassembled, plug in the instrument and verify the E6601A is operating properly.

The service procedure E6601A-01 is now complete.