

E6640A-04

## Modification Recommended Service Note

Supersedes: [ NONE]

## E6640A Wireless test set

Serial Numbers: all

The Problem

When replacing an M9037A with the new M9035A you will have to replace the M9018A/B chassis with a new M9019A chassis and load firmware version E.28.09 or greater. Charges only apply to the cost of the new M9019A chassis when no more M9037A parts are available

 Parts Required:
 Description
 Qty.

 M9019-66101
 M9019A PXIe Chassis Assembly, 18-slot
 1

## ADMINISTRATIVE INFORMATION

ACTION	[X] ON SPECIFIED FAILURE	STANDARDS
CATEGORY:	[]] AGREEABLE TIME	LABOR: 1.0 Hours
LOCATION CATEGORY:	[[]] ON-SITE (active On-site contract required) X SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [[]] SEE TEXT [[]] SEE TEXT
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 1 Dec 2028
	[]] Calibration Required X Calibration NOT Required	PRODUCT LINE: PL13 AUTHOR: MJW

ADDITIONAL INFORMATION:

Charges only apply to the cost of the new M9019A chassis when no more M9037A parts are available



Situation:

When replacing an M9037A with the new M9035A you will have to replace the M9018A/B chassis with a new M9019A chassis and load firmware version E.28.09 or greater. The M9035A is not backwards compatible with the M9018A & B chassis.

This only applies to controller failures when no more M9037A parts are available:

 E6640-61802 - M9037A Controller kit imaged with Operating System and E6640A software are out of stock

Solution/Action:

Replaced the M9018A or M9018B chassis with a new M9019A chassis (PN:M9019-66101) Update instrument software to E.28.09 or greater

Revision History:

Date	Service Note Revision	Author	Reason for Change
7 November 2022	01	Michael Woichik	As Published