E8267D-22A-S

Safety Service Note

Implemented During Normal Course of Providing Support

> Supersedes: E8267D-22-S

E8267D - Digital Signal Generator

Serial Numbers: MY0000000-MY49060130, MY40960132-MY49060157, MY49060161-MY49060210, MY49060212-MY49060213, MY49060215-MY49060220, MY49060222-MY49060224, MY49060226-MY49060235, MY49060237-MY49060238, SG0000000-SG49060029, US0000000-US49060141, US49060143-US49060173, US49060175-US49060190, US49060193-US49060199, US49060203, US49060212

POSSIBLE "SHOCK PINCH" HAZARD

WARNING HAZARD CLASS "(2)"

Potential Safety hazard due to E8267D Line Module

Parts Required:

P/NDescriptionQty.9135-5695Line module with cable assembly1

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 1.0 Hours		
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) [X] SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [X] SCRAP PARTS: [X] SCRAP [[]] SEE TEXT [[]] SEE TEXT		
AVAILABILITY:	: EOS	NO CHARGE AVAILABLE UNTIL: ALWAYS		
	[[]] Calibration Required [X] Calibration NOT Required	PRODUCT LINE: 15 AUTHOR: PY		

ADDITIONAL INFORMATION:



Situation:

During a recent new product evaluation, it was found that one E8267D failed to properly start up. The fault was found to be a loose (unsatisfactory) crimp on one of the hot/neutral line module wires inside the instrument. This poor crimp did not ensure a secure electrical connection from the AC line to the power supply. The earth ground was still securely in place. Additional shock and vibration testing demonstrated that the bottom cover and main PC board mechanically restrain these wires from pulling free of the connector and contacting the instrument chassis. Therefore, this is not a safety issue for an instrument user. The earth ground connection within the instrument is a separate wire and is securely held in place with a bolt and nut to the instrument chassis to ensure the user's safety.

All part, 9135-5695 line modules have been purged from stock.

All new and replacement line modules are corrected.

Solution/Action:

Please contact your local Keysight Technologies Sales and Service to make arrangements to have the instrument returned for service.

Revision History:

Date	Service Note Revision	Author	Reason for Change	
14 Oct 2010	01	Son Nguyen	As Published	
15 Sep 2020	02	Petrina Yong	Extend Service note till EOS	