E8356A-01

S E R V I C E N O T E

Supersedes: NONE

E835xA PNA RF Network Analyzers

Serial Numbers: US00000000 thru US41089999

Failures of the Noise Floor and/or Crosstalk performance tests are often caused by deterioration of the rubber receiver gaskets. In case of failures, replace with metal waffle gaskets.

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

P/NDescriptionQty.N3381-20032metal waffle gasket4

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	[[]] IMMEDIATELY X ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS: LABOR: 1.0 Hours
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE X ON-SITE X SERVICE CENTER	SERVICE [[]] RETURN USED [[]] RETURN INVENTORY: X SCRAP PARTS: X SCRAP [[]] SEE TEXT [[]] SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: PROD'S SUPPORT LIFE
AUTHOR: LSH	PRODUCT LINE: WN	
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2005 PRINTED IN U.S.A.



Page 2 of 2 E8358A-01

Situation:

When an E875xA PNA fails the Crosstalk or Noise Floor tests, the failure may be a caused by deteriorated rubber gaskets on the receivers. If the gaskets are the rubber type, they should be replaced. It is difficult to determine the gasket material type without removing the cover on the receiver. See page 7-30 in the service manual (E8356-90002) for instructions.

Solution/Action:

If test failures indicate a problem and the old rubber gaskets are in place, then replace all four gaskets. One on each receiver.

Following the gasket replacement, a full set of performance tests should be performed.