E8363C-04 <u>S E R V I C E N O T E</u>

Supersedes: NONE

E8363C PNA Microwave Network Analyzers

Serial Numbers: "[US00000000 / US99999999] or ALL"

An enhancement added to absorb vibration when opening the swing deck during hardware repair.


Parts Required: P/N	Description	Qty.
E8361-40001	Bumper	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
MODIFICATION RECOMMENDED				
ACTION CATEGORY:	X AGREEABLE TIME	STANDARDS LABOR: 0.5 Hours		
LOCATION CATEGORY:	X ON-SITE X SERVICE CENTER	SERVICE INVENTORY: N/A	USED PARTS: N/A	
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 01-JAN-2011		
AUTHOR: DYCS		PRODUCT LINE: WN		
ADDITIONAL IN	FORMATION: This Service Note applies to		/C, E8362/3/4B/C and	

E8362/3/4B/C-H85. Please refer to the Service Guide for troubleshooting procedure.

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.





Situation:

A bumper is available to enhance the serviceability and to protect nearby assembly from swing deck.

Solution/Action:

A rubber bumper – E8361-40001 is available to improve the serviceability of the instrument. This will also ensure the swing deck well separated from other nearby assembly.

Refer to the PNA Service Guide for instruction on removing the PNA front panel. To view this Service Guide information, use the following steps:

- 1. Go to http://na.tm.agilent.com/pna/documents.html.
- 2. Click on the appropriate Service Guide.
- 3. When the PDF of the Service Guide is displayed, look at the bookmarks in the left column. Expand the Contents section by clicking on the plus sign next to its bookmark.
- 4. Scroll through the Contents section bookmarks to locate "Repair & Replacement Procedures."
- 5. Click on the title/hyperlink for the section "Receiver Deck."
- 6. Follow the instructions in the subsection "Raising and Lowering the Receiver Deck."
- 7. Once the Receiver Deck has been lower, installed the Bumper as shown in Figure 2.

Figure 1






Figure 3






Figure 5

