

SAFETY – IMPLEMENTED DURING NORMAL COURSE
OF PROVIDING SUPPORT

M9505A-05A-S

S E R V I C E N O T E

Supersedes:
M9505A-05-S

M9505A AXIe 5 Slot Chassis

Serial Numbers: TW00000000 through TW54260100.

Exceptions: TW51120208, TW51440215, TW52060203, TW52070203, TW52070205, TW53360161, TW53360168, TW53360170, TW53360185, TW54010104, TW54010173, TW54010175, TW54010183, TW54010200, TW54010204 through TW54010219, TW54010221, TW54010238, TW54010240 through TW54010242, TW54010244 through TW54010247, TW54060101 through TW54060103, and TW54180101 through TW54180109

POSSIBLE DROP HAZARD

WARNING

HAZARD CLASS 1

Chassis carry handle may come off while handling

Parts Required:

P/N	Description	Qty.
M9502-80011	M9502A and M9505A Handle Screw Kit	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
SAFETY			
ACTION CATEGORY: X AGREEABLE TIME		STANDARDS LABOR: 0.5 Hour	
LOCATION CATEGORY: <input type="checkbox"/> ON-SITE (active On-site contract required) <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	X RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: ALWAYS		NO CHARGE AVAILABLE UNTIL: EOS	
<input type="checkbox"/> Calibration Required <input checked="" type="checkbox"/> Calibration NOT Required		PRODUCT LINE: BL AUTHOR: TP	
ADDITIONAL INFORMATION:			

Situation:

Chassis carry handle screws may become loose over time causing the carry handle to come off while handling.

Solution/Action:

Carry handle screws with locking mechanism will prevent this issue. Picture below shows the screw with locking mechanism included in the M9502A and M9505A Handle Screw Kit (M9502-80011).



Replace the screws on the chassis carry handle. Tighten the handle screws to 23-25 kgf.cm (20-22 in-lbs). Perform the same step to replace the screws on the second carry handle on the other side of the chassis.

Revision History:

Service note Revision	Date	Author	Reason For Change
1.0	9/18/13	TP	As published
2.0	11/21/14	TP	Update to new screw kit