MSOS404A-03D

Modification Recommended Service Note

Supersedes: MSOS404A-03C

MSOS404A – MSO Infiniium S Series 4GHz 4 channel

Serial Numbers: MY00000001-MY58060101; SG55160101, SG55160102, SG55360101, SG55380101, SG55380102, SG55510101, SG55510103, SG57220101-SG57220107, SG58150101-SG58150110, SG59320101

The Problem – Under certain circumstances a PLL2 error may occur on the S-series products.

Parts Required: P/N	Description	Qty.
54911-69511 54911-69521 54911-69531	PCA – Acquisition Board (tested) PCA – Acquisition Board (tested) PCA – Acquisition Board (tested)	1 1 1
54911-69532	PCA – Acquisition Board (tested)	1

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 4.0 Hours
LOCATION CATEGORY:	 [[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) [X] SERVICE CENTER [[]] CHANNEL PARTNERS 	SERVICE: [X] RETURN USED [X] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [[]] SEE TEXT [[]] SEE TEXT
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: December 31, 2022
	[X] Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: PL-1A AUTHOR: EG

ADDITIONAL INFORMATION:



Situation:

On older acquisition boards a PLL2 error message sometimes occurs. The error message appears on the screen as below:



There are new acquisition boards that fix this issue for the S-series scopes.

Solution/Action:

Please, use the 54911-69511 board until is gone. If you have a 54911-69511, then skip steps 1 and 2 and proceed to step 3. If there are no 54911-69511, then start with step 1 below.

- 1. If the customer needs to have software revision < 6.10.01001, then replace the acquisition board with the 54911-69532 board.
- 2. If the customer can have software revision >= 6.10.01001, then it can be replaced by any of these three boards: 54911-69521, 54911-69531, or 54911-69532.
- 3. Save the Serial Numbers of the replaced and the new Acquisition Boards in Siebel. Please, follow this procedure:
 - a. For each Service Order in Siebel, there is a tab labeled Activities:

Activities	Menu 👻 Query				
Activity #	Туре	Billing Type	Planned Start	Duration	Status
1-40WC9AU	Logistics	Not Billable	3/22/2017 12:20:53		Done
1-40WC9AX	Repair-Inc post C	Factory Warranty	3/22/2017 12:20:53		Done

b. Clicking on the Activity # associated with the Repair, you'll see this:

Menu 🔻	New Qu	env					
Туре	Date		Labor Item Number	Quoted Time	Elapsed Time	Reported Time	Original
Standard Time	4/18/2017	7	RLR5A		4.00	4.00	
Standard Time	4/18/2017	7	RLR5C		1.50	1.50	

c. Click on the Items tab to enter or see the parts that were ordered and/or used:

Menu 🔻	New Query Split L	ine			
Part #	Product Description	Alternate Product Des	Qty	Original List Price	Extended Amount
16800-68702	Power supply subass	Netzteil Untereinhe	1		
0950-4822	Power Supply 15-WA	Ň	1		
0960-2875	NFTS; Mod and Ser	N	1		
0960-2939	Mod and Ser Nbr Re	q	1		

d. Somewhere in the parts record you'll find the serial number fields (Old Serial Number, and New Serial/Mfg Id)

New Serial/Mfg Id	Planned Date	Return Ship Date	Tracking #	Location	Product Line	Line Comment	Include in Billable Tot	Old Serial Number	Refe
	4/12/2017 09:47:11				8T		~		
	4/6/2017 17:23:31				8T		~		
	4/12/2017 10:32:47				8T		~		
	4/10/2017 16:34:16				8T		~		

e. The fields can be re-ordered in Siebel so that they are more easily found – like this:

More Info	Attachments Assign	Contacts Emp	loyees Too	is Charges Items	Messages	Time	Logistics	Audit Trail	CFD Language	
Menu 🔻	New Query Spli	t Line								
Part #	Product Description	Alternate Produc	t Det Qty	Parts Fail Code	Old Seria	al Number	Return T	Го	New Serial/Mfg Id	Orig
16800-68702	Power supply suba	ss/Netzteil Unterein	he 1	Defective Assen	nbl		Distribut	ion Center		
0950-4822	Power Supply 15-V	VA	1	Assembly/Part N	Not	•	Distribut	ion Center		
0960-2875	NFTS; Mod and Se	er N	1	Assembly/Part N	Not		Distribut	ion Center		
0960-2939	Mod and Ser Nbr F	Req	1	Assembly/Part N	Not		Distribut	ion Center		

NOTE: The fields only take 19 characters. The acq board serial numbers are 24 characters. Please do not enter the "54911" portion of the serial numbers (the first 5 numbers) in the fields; enter only the remaining 19 characters.

Adding the serial numbers of both the failed (replaced/old) Acquisition Board and the new Acquisition Board in these fields will allow us to more easily find them in Siebel and Spotfire.

4. Return the failed acquisition board to the factory.

Revision History:

Date	Service Note Revision	Author	Reason for Change
30 Jan 2018	03	Ed Gorbea	As Published
18 Apr 2018	03A	Ed Gorbea	New acquisition board
28 Feb 2019	03B	Ed Gorbea	More new acquisition boards
24 Apr 2019	03C	Ed Gorbea	Adding 54911-66/69511 board
14 Oct 2019	03D	Ed Gorbea	Adding SGXXXXXXX models