

MSOS804A-04

# Modification Recommended Service Note

Supersedes: NONE

# MSOS804A – MSO Infiniium S Series 8GHz 4 channel

Serial Numbers: MY58060105 to MY58060107, MY58120107, MY58120111

**The Problem** – A pair of resistors were placed in the wrong location on the VCO circuitry.

Parts Required:				
P/N	Description	Qty.		
54911-69511 or 54911-69521	PCA – Acquisition Board (Tested)	1		

#### ADMINISTRATIVE INFORMATION

ACTION	[X] ON SPECIFIED FAILURE	STANDARDS	
CATEGORY:	[[]] AGREEABLE TIME	LABOR: 4.0 Hours	
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) [X] SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: [X] RETURN USED [X] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [[]] SEE TEXT [[]] SEE TEXT	
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: June 2020	
[X] Calibration Required		PRODUCT LINE: PL-1A	
[[]] Calibration NOT Required		AUTHOR: EG	

ADDITIONAL INFORMATION:



## Situation:

Two resistors were placed in the wrong position on the VCO circuitry, therefore the acquisition board will need to be replaced in these units even if no failures are found.

## Solution/Action:

Replace the acquisition boards with the ones mentioned above only if they also have the acquisition board mentioned on the table below. Otherwise, assume that the acquisition board has already been replaced and do not proceed with this Service Note.

If the oscilloscope meets the requirements as stated on the paragraph above, then enter the serial number if the acquisition board in Siebel. Here's a list of the faulty units along with their faulty acquisition boards.

Model	Scope S/N	Board S/N
MSOS804A	MY58060105	54911664010652320174400114
	MY58060106	54911664010652320174500141
	MY58060107	54911664010652320174000142
	MY58120107	54911664010642320172700049
	MY58120111	54911664010642320173100082

Revision History:			
	Service		
Date	Note	Author	Reason for Change
	Revision		
07 Jun 2018	01	Ed Gorbea	As Published