

MX0025A-01

Modification Recommended Service Note

Supersedes:
None

InfiniiMax Ultra 25 GHz Probe Amp with AutoProbe 2 Interface

Serial Numbers: US61180202, US61180204, US61180214 - US61180219

The Problem – The early shipments of MX0025A probes have been found to have a quality concern that can cause probes to not be recognized when attached to the scope channel.

Parts Required: NA

ADMINISTRATIVE INFORMATION

ACTION	XX ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	<input type="checkbox"/> AGREEABLE TIME	LABOR:	0.2 Hours		
LOCATION	<input type="checkbox"/> CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN	USED	XX RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP	PARTS:	<input type="checkbox"/> SCRAP
	XX SERVICE CENTER		<input type="checkbox"/> SEE TEXT		<input type="checkbox"/> SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS				
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	December. 20 th 2023		
	XX Calibration Required	PRODUCT LINE:	PL1		
	<input type="checkbox"/> Calibration NOT Required	AUTHOR:	MR		


ADDITIONAL INFORMATION: This SN is issued to repair this concern and not replace with new MX0025A probes. (UE2 Strategy)

Situation:

The early shipments of MX0025A probes have a quality concern that can cause probes to not be recognized when attached to the scope channel. Please see Figure 1.

- 1. Capacitor failure

Figure 1.



Solution/Action:

Please return defective probe amplifier to service center for repair.

Revision History:

Date	Service Note Revision	Author	Reason for Change
9 Dec. 2021	01	Mark Rowley	As Published