# Modification Recommended Service Note

Supersedes: N3307A-01

# N3307A DC Electronic Load Module

Serial Numbers: Refer to Table 1

The Problem – There is an offset value in voltage and current parameter observed for the N3300 series module. The reading values drifted to larger value (with nothing connected) after the unit warmed up.

# Parts Required:

P/N	Description	Qty.
N3307-61061	DC Electronic Load Module, 0-150V, 30A, 250W, 1 slot, Lead Free	1
OR		
N3307_61071	DC Flectronic Load Module, 0-150V, 30A, 250W, 1 slot, LIKCA, Lead Free, MY SN	1

#### ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 0.5 Hours		
LOCATION CATEGORY:	[X] SERVICE CENTER [[]] ON-SITE (active On-site contract required) [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [X] RETURN INVENTORY: [[]] SCRAP [X] SEE TEXT [[]] SEE TEXT		
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 27 <sup>th</sup> June 2023		
	[[]] Calibration Required [X] Calibration NOT Required	PRODUCT LINE: SP AUTHOR: LIM ZHAN MING		

ADDITIONAL INFORMATION: Service inventory no impacted



# Situation:

For the Serial Number listed in Table 1, unit may observe offset value in voltage and current parameter. The reading values drifted to larger value (with nothing connected).

# Solution/Action:

Please contact local Keysight call center to get a replacement unit.

Table 1: Affected Serial Number

MY57012246	MY57012254	MY57012261	MY57012267	MY57012273
MY57012248	MY57012255	MY57012262	MY57012268	MY57012274
MY57012250	MY57012256	MY57012263	MY57012269	
MY57012251	MY57012257	MY57012264	MY57012270	
MY57012252	MY57012258	MY57012265	MY57012271	
MY57012253	MY57012260	MY57012266	MY57012272	

# Revision History:

Date	Service Note Revision	Author	Reason for Change
28 <sup>th</sup> June 2022	01	LIM ZHAN MING	As Published
15 <sup>th</sup> April 2023	02	LIM ZHAN MING	Revised serial number and part number