N4391A-03

Modification Recommended Service Note

Supersedes: NONE

N4391A - Optical Modulation Analyzer

Serial Numbers: DE49900181

Performance improvement for dual scope OMA to solve unreliable synchronization between the two oscilloscopes

Parts Required:

P/N Description Qty.

None - Modification will be done at factory → RTF

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[[]] ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS LABOR: 0.5 Hours for admin
LOCATION CATEGORY:	 [[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) X KEYSIGHT LOCATION → RTF [[]] CHANNEL PARTNERS 	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP X None → RTF X None → RTF
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 30-Apr-2018
	X Calibration Required → included in RTF service [[]] Calibration NOT Required	PRODUCT LINE: 3E AUTHOR: jm

ADDITIONAL INFORMATION:

The implementation of the recommended modification service note will be done at the factory \rightarrow RTF.



Situation:

The scope synchronization software (external and internal) of this dual scope OMA system does not provide a reliable synchronization between the oscilloscopes. In case of an unreliable synchronization the OMA system delivers totally unreasonable results.

Solution/Action:

To have best performance and reliable synchronization for the OMA systems Keysight is offering and recommending this free-of-charge (until Apr-2018) service for the identified system.

Send in your OMA system to your next Keysight service location to implement the new auto calibration feature (hardware upgrade at factory \rightarrow RTF) which solves the described synchronization behavior. A subsequent system calibration at factory is included.

Revision History:

Date	Service Note Revision	Author	Reason for Change	
13 Sep 2016	01	jm	As Published	