# Information Only Service Note

Supersedes: N5166B-03

# N5166B X-Series CXG Vector Signal Generator

Serial Numbers: ALL

The Problem - A3 RF assembly boards showing Heater and Unlock errors

Parts Required:

P/N Description Qty.

NONE

#### ADMINISTRATIVE INFORMATION

[[]] Calibration Required PRODUCT LINE: 15
X Calibration NOT Required AUTHOR: PY


ADDITIONAL INFORMATION:



#### Situation:

Recently we noticed several A3 RF Assemblies return to factory with the following Heater and Unlock errors at the Annunciators area. It can also include errors 619, FPGA revision is invalid. Do refer to Figure 1a and 1b for the details.

Figure 1a - Heater and Unlock Errors with Invalid FPGA Rev #



Or






Figure 1b - Multiple Error 619





#### Solution/Action:

This Service Note is to emphasize on the proper handling of the A3 RF Assembly board, from removal of the assembly from the carton box, handling on the workbench to removal from instrument and the replacement procedure.

### A. Removal from the carton box

Below figures 3 and 4 shows the correct and incorrect method to remove the A3 RF assembly board from the carton box.



Figure 3





Figure 4

# B. While working with the board

Avoid tilting the board where components touches the workbench. This would give pressure on the PCA and potentially can damaged the PCA as well as the components in the area. Always lay the board flat on the workbench. Refer to Figure 5.




Figure 5

Figure 6 shows the correct and incorrect method of holding the board while removing and fixing the fixture.





Figure 6

## C. Removal from the instrument

Pry slots are provided on both sides of the A3 RF assembly to aid in removing of the board. Use a flat head (a wedge-shaped flat tip) screwdriver to loosen the board from the chassis as shown in Figure 7.




Figure 7

Figure 8 shows the correct and incorrect method of holding the board while removing and installing the board to the instrument.




Figure 8

Another precaution is when removing and reinstalling back the screw (refer to Figure 9), it is not necessary to remove the ribbon cable to avoid re-attaching the ribbon cable back.




Figure 9

This service note is to complement the X-Series Signal Generator Service Guide (N5180-90059), Assembly Replacement Section for A3 RF assembly.

# Revision History:

Date	Service Note Revision	Author	Reason for Change
13 Dec 2022	01	Petrina Yong	As Published
14 June 2023	02	Petrina Yong	Added more handling procedure