

N5172B-03B

# Information Only Service Note

Supersedes: N5172B-03A

# N5172B X-Series EXG Vector Signal Generator

Serial Numbers: ALL

The Problem – Installing a new A3 RF Assembly during a repair may require the installation of a newer version of instrument firmware.

## Parts Required:

P/N Description Qty.

NONE

Х

#### ADMINISTRATIVE INFORMATION

[[]] Calibration Required Calibration NOT Required **PRODUCT LINE: 15** AUTHOR: MM

ADDITIONAL INFORMATION:



#### Situation:

The A3 RF assemblies in the X-Series family of signal generators has gone through a few changes over the years. These changes have typically been made to either improve reliability or replace lower level components that have been discontinued. When changes such as this are made the part number of the assembly will typically be changed. Some changes also require that the instrument firmware be updated to recognize and control them properly. In these cases, the instrument firmware may need to be updated when the assembly is replaced during servicing. If the firmware is not updated in these cases, instrument configuration errors may be seen, installed options may not function properly, service software may give errors, and self-test errors can occur.

While the A3 RF assembly part number has changed over time, the replacement kits have maintained the same ordering part numbers.

### Solution/Action:

Under normal circumstances it is always recommended that the latest firmware be installed in Keysight products to maintain the most current functionality and performance, as well as proper operation. However, there are times when the customer does not want their instrument firmware to be updated.

Table 1 lists the possible A3 RF assembly part numbers that could be installed in an N5172B signal generator, along with any minimum firmware revision requirement for them. These are the part numbers that can be found on the **Utility**, **Instrument Info**, **Installed Board Info** screen of the instrument, as shown in Figure 1.

Hardware ID	Minimum Firmware Requirement
0002	Any
0002	Any
0002	Any
0002	Any
0006	B.01.65
0009	B.01.96
0006	B.01.65
0009	B.01.96
	0002 0002 0002 0002 0002 0006 0009 0006

#### Table 1 – A3 RF Assembly Hardware versus Firmware

For the latest information on the correct kit part number to order when replacing an A3 RF assembly, see Chapter 14, Replacement Parts in the instrument service guide (N5180-90059.pdf).

When an exchange assembly is ordered, the A3 RF assembly that comes in the kit could be any one of the exchange part numbers listed in Table 1, so the minimum firmware requirement may vary depending on the part received.

FREQUENCY 6.0	00 000 00	0 000 GHz	re off 2 -144.	.00 dBm	Board Info
Installed Bo Name	oard Information Part#/Rev#	Serial#	HUID OFR PIC	Opts Extr	
RF Analog PCI FP0 Ref FP0 Synth F	FPGA 7,1db0,150 A 7,0130,000 A 2,12ba,133	)0:feb9 la:da2a	0002 002	0000 0000	
BB IF FPGA BBG FP0 Memory	2,1462,112		0000 000 000	0000 0000	

To download the latest version of the EXG firmware go to http://www.keysight.com/find/exg\_firmware

#### Revision History:

Date	Service Note Revision	Author	Reason for Change	
11 Aug 2017	01	Allen Stephens	As Published	
16 Oct 2018	02	Mike Medley	Updated information	
01 April 2022	03	Mike Medley	Updated to add latest requirements	

© Keysight Technologies 2015-2022 Information Only Service Note Version 1.2 | April 1, 2022| Page **4** of **4**