N5173B-09

# Information Only Service Note

Supersedes: None

## N5173B X-Series EXG µWave Signal Generator

Serial Numbers: ALL

The Problem – Self-test #104 failure if replacing either the A3 RF Assembly with Hardware ID 000B or the A7 Micro-deck containing A7A1 ALC control board with hardware ID 0002 is not upgraded to the minimum FW B.01.96.

#### Parts Required:

P/N Description Qty.

NONE

#### ADMINISTRATIVE INFORMATION

[[]] Calibration Required PRODUCT LINE: 15
X Calibration NOT Required AUTHOR: PY


ADDITIONAL INFORMATION:



#### Situation:


The A3 RF assemblies and A7A1 ALC control board on the A7 micro-deck were enhanced to support a new 12bit ADC for assurance of supply (AOS). Replacement of either the A3 RF Assembly, N5180-60173 with Hardware ID 000B or the A7 Micro-deck containing A7A1 ALC control board, N5180-60172 with Hardware ID 0002 will require minimum FW B.01.96 for it to operate properly. Multiple self-test failures can be observed after completing the self- test, as shown in Figure 1.

Figure 1 - Multiple self-test failures



First, check that the hardware ID for the replaced assembly. This can be found on the **Utility**, **Instrument Info**, **Installed Board Info** screen of the instrument, as shown in Figure 2.

Figure 2 - Installed Board Information Screen



Factory has also made an identification on this firmware requirement.


On the RF assembly, a label "minimum FW B.1.96" will be pasted on the shield, as shown in Figure 3.

Figure 3 – Location of label on the RF assembly



On the micro-deck, a label "minimum FW B.1.96" will be pasted on the ALC control board as shown in Figure 4.

Figure 4 – Location of label on the ALC control board



Sol			/ A	-4:		-
$\sim$	HITI	$^{\circ}$	/ 🛆	CTI	Λn	-

Upgrade the instrument firmware to B.01.96. Go to <a href="http://www.keysight.com/find/exg\_firmware">http://www.keysight.com/find/exg\_firmware</a> to download the instrument firmware.

Once the firmware successfully upgraded, verify that the self-test is passing on the instrument.

### Revision History:

Date	Service Note Revision	Author	Reason for Change	
26 Apr 2022	01	Petrina Yong	As Published	