

N5182B-05B

Information Only Service Note

Supersedes:
N5182B-05A

N5182B X-Series MXG Vector Signal Generator

Serial Numbers: ALL

The Problem – Installing a new A3 RF Assembly during a repair may require the installation of a newer version of instrument firmware.

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

<input type="checkbox"/>	Calibration Required
X	Calibration NOT Required

PRODUCT LINE: 15
AUTHOR: MM

ADDITIONAL INFORMATION:

Situation:

The A3 RF assemblies in the X-Series family of signal generators has gone through a few changes over the years. These changes have typically been made to either improve reliability or replace lower level components that have been discontinued. When changes such as this are made the part number of the assembly will typically be changed. Some changes also require that the instrument firmware be updated to recognize and control them properly. In these cases, the instrument firmware may need to be updated when the assembly is replaced during servicing. If the firmware is not updated in these cases, instrument configuration errors may be seen, installed options may not function properly, service software may give errors, and self-test errors can occur.

While the A3 RF assembly part number has changed over time, the replacement kits have maintained the same ordering part numbers.

Solution/Action:

Under normal circumstances it is always recommended that the latest firmware be installed in Keysight products to maintain the most current functionality and performance, as well as proper operation. However, there are times when the customer does not want their instrument firmware to be updated.

Table 1 lists the possible A3 RF assembly part numbers that could be installed in an N5182B signal generator, along with any minimum firmware revision requirement for them. These are the part numbers that can be found on the **Utility, Instrument Info, Installed Board Info** screen of the instrument, as shown in Figure 1.

Table 1 – A3 RF Assembly Hardware versus Firmware

A3 RF Assembly Part Number	Hardware ID	Minimum Firmware Requirement
N5180-60150	0000	Any
N5180-69150	0000	Any
N5180-60238	0000	Any
N5180-69238	0000	Any
N5180-60278	0005	B.01.65
N5180-69278	0005	B.01.65
N5180-60296	0005	B.01.65
	0008	B.01.96
N5180-69296	0005	B.01.65
	0008	B.01.96

For the latest information on the correct kit part number to order when replacing an A3 RF assembly, see Chapter 14, Replacement Parts in the instrument service guide ([N5180-90059.pdf](#)).

When an exchange assembly is ordered, the A3 RF assembly that comes in the kit could be any one of the exchange part numbers listed in Table 1, so the minimum firmware requirement may vary depending on the part received.

Figure 1 – Installed Board Information Screen

FREQUENCY		RF OFF		Board Info	
6.000 000 000 000 GHz		-144.00 dBm			
Installed Board Information					
Name	Part#/Rev#	Serial#	HUID	OFB	PIC Opts Extr
RF	N5180-60238	23130600003	0000	000	000 0000
Analog FPGA	7,1db0,1501:cd38				
PCI FPGA	7,0130,0000:feb9				
Ref FPGA	2,12ba,131a:da2a				
Synth FPGA	12d,0000,0000:0000				
BB	N5180-60145	23125000041	0000	000	000 0000
IF FPGA	2,1462,112e:da60				
BBG FPGA	40d4,01a3,1208:ec45				
Memory	2GB + 2GB				

To download the latest version of MXG firmware go to http://www.keysight.com/find/mxg_firmware

Revision History:

Date	Service Note Revision	Author	Reason for Change
11 Aug 2017	01	Allen Stephens	As Published
16 Oct 2018	02	Mike Medley	Updated information

01 Aug 2020

03

Mike Medley

Updated to add latest requirements
