

MODIFICATION RECOMMENDED

# N5230A-RECALL-01A

## S E R V I C E N O T E

Supersedes: N5230A-RECALL-01

### N5230A – Performance Network Analyzer (PNA)

**Serial Numbers:** MY45001652, US43500322, MY45000918, MY46400293, US43500572,  
US43500437, MY45000727, MY46400455, MY46400305

**Calibrations performed on some 4-Port Performance Network Analyzers by Agilent Technologies between April 01, 2010 and April 07, 2011 show a false pass in the test summary for the calibration coefficients test.**

**Parts Required:**

P/N	Description	Qty.
NONE		

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: <b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 1.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 01-April-2012	
AUTHOR:	MW	PRODUCT LINE: **	
ADDITIONAL INFORMATION: Gratis Support need to be chosen as the billing type, while creating the customer order.			

© AGILENT TECHNOLOGIES, INC. 2011  
PRINTED IN U.S.A.

May 4, 2011

Rev. 18



**Situation:**

The Quality issue is caused by a Test-Software defect which overrides the ports 1&2 test result with the test result of ports 3&4 in cases where test points of port 1&2 are either failed or indeterminate. Agilent corrected the PNA Calibration Test Software and installed it on all Test Systems by April 4, 2011.

**Solution/Action:**

1. Customer, please contact nearest Agilent Customer Care Center and send instrument to Agilent for free calibration.
2. Agilent WCSS Service & Support to calibrate affected products at Agilent's expense.
3. After re-calibration Agilent to send the instrument back to the customer.