

N5768A-06A

Modification Recommended Service Note Supersedes:

N5768A-06

N5768A - DC System Power Supply, 80V, 19A, 1520W

Serial Numbers: US14F0001A - US15L9999Z

All "B" prefixed firmware versions prior to B.00.07 need to be updated to B.00.07 (8/5/2015), or later. This update addresses a recently discovered quality issue which is not related to the safety of the user or the product. Under certain specific/unique conditions, the product may not turn-on to Factory Default values as indicated in the User's Guide.

A formal Keysight "Quality Issue Notification" has been mailed to all individual customers of record, whose instruments might contain early, "B" version firmware. The User's Guide now includes an appropriate CAUTION statement for this unique corner condition.

"A" version firmware is NOT subject to this issue and CANNOT be updated to a "B" version.

ADMINISTRATIVE INFORMATION

ACTION	[]] ON SPECIFIED FAILURE	STANDARDS
CATEGORY:	X AGREEABLE TIME	LABOR: 0.25 Hours
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE X ON-SITE (active On-site contract required) X SERVICE CENTER X CHANNEL PARTNERS	SERVICE [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [[]] SEE TEXT [[]] SEE TEXT
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: EOS
	[]] Calibration Required X Calibration NOT Required	PRODUCT LINE: SP AUTHOR: P.F.

ADDITIONAL INFORMATION:

Parts Required: NONE

The required B.00.07 version Firmware and Installation Utility are both available from the Web @ http://www.keysight.com/find/n5700firmware

Situation:

ONLY in the Safe-Start turn-on mode; after initial AC turn-on and immediately following boot-up completion, a short duration (~3.5 seconds) time-exposure window begins. Within this window, if the [OUT ON] Key is struck; the described quality issue *could* become realized.

IF the described conditions have been set in motion, in the order and timeframe described, the DC output voltage *could* assume a level other than zero for the remainder of the exposure window. This quality issue can only occur once, during a single AC turn-on user session.

IF the [OUT ON] Key is struck, any time after the close of the exposure window, product behavior will be as described in the User's Guide (i.e., factory default, "*RST" conditions, output voltage zero).

Solution/Action:

Visually, only instruments with scrolling "8's" during boot-up are potential candidates for this firmware update. "*IDN?" should be used to confirm the actual requirement for this update. Instruments that boot-up with "IEEE" will not demonstrate this guality issue.

Update firmware, as required, from Web site http://www.keysight.com/find/n5700firmware. This web site contains BOTH the necessary firmware and a utility which will determine the existing firmware version and provide/install the required update, as necessary.

A "CAUTION" note regarding this behavior has been added to the Keysight Series N5700 User's Guide (5969-2917), on the appropriate pages.

Revision History:						
Date	Service Note Revisio	Author	Reason for Change			
09 Oct 2015	01	JOC/PF	As Published			
15 Jan 2016	02	JOC/PF	Revised serial numbers			



