N6761A-02 <u>S E R V I C E N O T E</u>

Supersedes: NONE

N6761A Precision DC Power Module

Serial Numbers: ALL

Firmware update will address an issue where N6700A, N6700B, N6701A and N6702A mainframes will not detect the 2UA Option during a query for the option information from the mainframe's menu as well as using the SCPI command SYST:CHAN:OPT? (@<chanlist>).

Parts Required: P/N

Qty.

NONE

ADMINISTRATIVE INFORMATION

Description

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	X ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 0.5 Hours	
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE X ON-SITE X SERVICE CENTER X CHANNEL PARTNER	SERVICE [[]] RETURN INVENTORY: [[]] SCRAP X SEE TEXT	USED [[]] RETURN PARTS: [[]] SCRAP X SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: End of Support	
AUTHOR: WIU		PRODUCT LINE: SP	
ADDITIONAL INFORMATION:			


© AGILENT TECHNOLOGIES, INC. 2008 PRINTED IN U.S.A.



Situation:

All N6700A, N6700B, N6701A and N6702A mainframes with a firmware revision lower then C.02.18 have the potential to not detect the 2UA Option during a query for the option information from the mainframe's menu as well as using the SCPI command SYST:CHAN:OPT? (@<chanlist>).

Figure 1. Mainframe is unable to detect Option 2UA



Solution/Action:

First, check the firmware revision of the N6700A, N6700B, N6701A or N6702A mainframe. To do this using one of the IO interfaces, send the "*IDN?" query.

Over the front panel, use the following sequence of key strokes:

Menu -> System -> About -> Frame. It will be listed under "Firmware revision." If the firmware revision is C.02.18 or higher, the unit has already been upgraded and no further upgrade is required.

If the firmware revision is older than C.02.18 then the firmware must be upgraded. All files, programs, and instructions required to upgrade the firmware are located at the following website: http://www.agilent.com/find/N6700firmware.