Modification Recommended Service Note

Supersedes: NONE

N7768A Optical Attenuator for Multimode Fiber (4 channels)

Serial Numbers: See Appendix

Potential data inconsistency causing measurement drift.

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

ACTION	[X] ON SPECIFIED FAILURE	STANDARDS		
CATEGORY:	[[]] AGREEABLE TIME	LABOR: 2.0 Hours		
LOCATION CATEGORY:	[X] SERVICE CENTER [[]] ON-SITE (active On-site contract required) [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [X] SEE TEXT [X] SEE TEXT		
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: December 31st 2024		
[X] Calibration Required		PRODUCT LINE: [3E]		
[[]] Calibration NOT Required		AUTHOR: [PG]		

ADDITIONAL INFORMATION:

Product must be returned to the factory for service note installation



Situation:

For the specific serial numbers listed in the appendix, it was determined that these instruments have been shipped with potential data inconsistency from one of the test equipment used causing measurement drift in certain test parameters.

Solution/Action:

Units will be adjusted and calibrated.

Please send the units back to Keysight for repair with reference information to this service note. Instruments must be returned to the factory for service note installation.

Revision History:

Date	Service Note Revision	Author	Reason for Change
26 Jun 2023	01	Pascal Grunge	As Published

Appendix:

MY50601518, MY50601519, MY50601522, MY50601525, MY50601526, MY50601538, MY50601541, MY50601553, MY50601554, MY50601555, MY50601556, MY50601557, MY50601561, MY50601564, MY50601568, MY50601570, MY50601571, MY50601581, MY50601583, MY50601593, MY50601595, MY50601601, MY50601603, MY50601610, MY50601611, MY50601614, MY50601617