N7977A-02

Modification Recommended Service Note

Supersedes: NONE

N7977A Advanced Power System – Dynamic DC Power Supply, 160 V, 12.5 A, 2000 W

Serial Numbers: MY540020150

The Problem – Non-RoHS compliance due to two leaded resistors.

Parts Required:

| P/N | Description | Qty. |
|-----------|--------------------------------------|------|
| 5067-5571 | Tested PCA Main Series Conn PBV 80V | 1 |
| 5067-5826 | Tested PCA Slave Series Conn PBV 80V | 1 |

ADMINISTRATIVE INFORMATION

| ACTION | [[]] ON SPECIFIED FAILURE | STANDARDS |
|-----------------------|---|---|
| CATEGORY: | [X] AGREEABLE TIME | LABOR: 1.5 Hours |
| LOCATION CATEGORY: | []] CUSTOMER INSTALLABLE []] ON-SITE (active On-site contract required) [X] SERVICE CENTER []] CHANNEL PARTNERS | SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [X] SCRAP PARTS: [X] SCRAP [[]] SEE TEXT [[]] SEE TEXT |
| AVAILABILITY | : PRODUCT'S SUPPORT LIFE | NO CHARGE AVAILABLE UNTIL: 1st December 2019 |
| | [X] Calibration Required [[]] Calibration NOT Required | PRODUCT LINE: SP AUTHOR: KHEW |

ADDITIONAL INFORMATION:



Situation:

N7977A was loaded with 2 pcs of leaded resistors. While this does not impact on the product functionality and long-term reliability; it is non-compliant to RoHS as N7977A is declared as RoHS compliant unit.

Solution/Action:

The impacted unit can be enhanced to RoHS Compliance by sending back to Keysight Service Center for Main (5067-5571) and Slave (5067-5826) PCA board replacement. Kindly contact Keysight Technologies Customer Contact Center at www.keysight.com/find/contactus.

Revision History:

| Date | Service Note Revision | Author | Reason for Change | |
|-------------|-----------------------------|--------|-------------------|--|
| 14 Nov 2018 | 01 | Khew | As Published | |