

N8262A-02

Modification Recommended Service Note

Supersedes: NONE

N8262A P-Series Modular Power Meter

Serial Numbers: MY47100102 / MY55490002 and SG47100101 / SG55106001

Intermittent LAN Connectivity

| Parts Required: P/N | Description | Qty. |
|-------------------------------|------------------------------|------|
| N8262-60203 | Cable Assembly- Internal LAN | 1 |

ADMINISTRATIVE INFORMATION

| ACTION CATEGORY: | []] ON SPECIFIED FAILURE X AGREEABLE TIME | STANDARDS LABOR: 0.5 Hours (Average) |
|-----------------------|--|---|
| LOCATION CATEGORY: | []] CUSTOMER INSTALLABLE []] ON-SITE (active On-site contract required) X SERVICE CENTER []] CHANNEL PARTNERS | SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: X SCRAP X SEE TEXT [[]] SEE TEXT |
| AVAILABILITY | : PRODUCT'S SUPPORT LIFE | NO CHARGE AVAILABLE UNTIL: 7-April-2017 |
| | [[]] Calibration Required X Calibration NOT Required | PRODUCT LINE: GM AUTHOR: AT |

ADDITIONAL INFORMATION:

Situation:

We have received report of some N8262A P-Series Modular Power Meter encountering intermittent connection loss. This has been identified due to the internal LAN cable.

This batch of LAN cable which is made of solid conductor (blue color) is more rigid and resistant to bending. It will be replace with a new enhance stranded conductor LAN cable (grey color) which is more flexible and suitable for bending application.

Only instruments within the serial numbers ranges identified in this Service Note are suspected of having this batch related LAN cable.

Solution/Action:


If an instruments identified on this Service Note is returned for calibration or repair, and this Service Note has not yet been applied, then the LAN cable will need to be replaced at that time.

To replace the Internal LAN cable:

- a) Remove instruments cover accordingly.
- b) Remove the cable tie on ferrite core.




c) Detached the LAN cable (N8262-60203@blue color) from PPMC Assembly (N8200-60002) and rear panel LAN port (1253-7195).






- d) Assemble new LAN cable (N8262-60203@grey color) to PPMC Assembly (N8200-60002) first and then assemble to rear panel LAN port (1253-7195).
- e) Tie ferrite core with cable tie and route cable as shown below.



f) Ensure LAN cable connection to PPMC Assembly (N8200-60002) and to rear panel LAN port (1253-7195) are latch properly.



| Date | Service Note Revision | Author | Reason for Change | |
|------------|-----------------------------|--------|-------------------|--|
| 7 Apr 2016 | 01 | AT | As Published | |