N9000A-07

Modification Available Performance Enhancement Service Note

Supersedes: NONE

N9000A CXA Signal Analyzer

Serial Numbers: MY54230695/MY54230778 MY55360013 This is the encompassing range. Check the specific affected ranges in the text.

Tighten the Screws on Shields of RF Board to Improve the Residual Response Performance

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

X Calibration Required [[]] Calibration NOT Required PRODUCT LINE: CM AUTHOR: KJ

ADDITIONAL INFORMATION:



© Keysight Technologies 2015-2018 Modification Available Service Note Version 1.2 | March 7, 2018| Page **1** of **3**

Situation:

The residual response (spurious) of N9000A in the range of 700 MHz to 900 MHz may impact some of the cellular applications although the performance meets the instrument specification.

Modification is available for the below list serial numbers (range) of N9000A CXAs to improve the residual response performance. MY54230695 MY54230714 MY54230752/MY54230754 MY54230762/MY54230763 MY54230767/MY54230769 MY54230772 MY54230775/MY54230778 MY55360013

Solution/Action:

1. Terminate the RF input of N9000A with 50 Ohm load. Set the N9000A to verify the typical residual response at 710 MHz.



2. Shutdown the CXA. Remove the CXA's RF Assembly as described in the "Assembly Replacement Procedures, RF Assembly, Removal" in the N9000A CXA Service Guide.



3. Place the RF Assembly properly.

4. Retighten the 34 screws on the shield of RF Assembly with torque of 1.5 Nm.

5. Reinstall the RF Assembly as described in the "Assembly Replacement Procedures, RF Assembly, Replacement" in the N9000A CXA Service Guide.

6. Perform the Adjustments and Performance Verification as described in "RF Assembly Changed/Repaired, Post Repair Testing Requirements" in N9000A CXA Service Guide.

Revision History:

Date	Service Note Revision	Author	Reason for Change
07 Mar 2018	01	KJ	As Published