

N9913A-02

S E R V I C E N O T E

Supersedes:
None

N9913A FieldFox Handheld Analyzer

Serial Numbers: Listed at end of note.

FieldFox instruments with the serial numbers listed on the following page may generate potential DANL failure due to different inductor being placed. A new RF board is required if DANL improvement is necessary.

Parts Required:

P/N	Description	Qty.
N9927-60200	RF Board Assembly for N9913A	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION X ON SPECIFIED FAILURE CATEGORY: <input type="checkbox"/> AGREEABLE TIME	STANDARDS LABOR: 3.0 Hours	
LOCATION X SERVICE CENTER (RETURN TO FACTORY) CATEGORY:	SERVICE <input type="checkbox"/> RETURN INVENTORY: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED <input type="checkbox"/> RETURN PARTS: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 18 April 2014	
X Calibration Required <input type="checkbox"/> Calibration NOT Required	PRODUCT LINE: WN AUTHOR: DYCS	
ADDITIONAL INFORMATION: <u>UNIT MUST BE RETURNED TO FACTORY FOR REPAIR.</u>		

© AGILENT TECHNOLOGIES, INC. 2013
PRINTED IN U.S.A.

April 12, 2013


Rev. 21



Situation:

FieldFox instruments with the serial numbers listed below may show potential DANL failures with 3-4 dB difference due to misloaded inductor on the RF board. If DANL improvement is necessary, a new RF board is available to fix this it.

Figure 1: Image showing the good and bad inductor on location U678 at RF Board

**Solution/Action:**

Affected FieldFox with necessary DANL improvement are required to send back to Agilent factory for a new RF board replacement. Test and Adjustment shall be done before shipping back to customer.

	Serial Numbers
1	MY52401241
2	MY52401269
3	MY52401277
4	SG52407000