N9918A-02

S E R V I C E N O T E

Supersedes: None

N9918A FieldFox Handheld Analyzer

Serial Numbers: Listed at end of note.

FieldFox instruments with the serial numbers listed on the following page may generate potential DANL failure due to different inductor being placed. A new RF board is required if DANL improvement is necessary.

Parts Required:

P/N Description Qty.

N9927-60111 RF Board Assembly for N9918A N9928A N9938A 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION X ON SPECIFIED FAILURE CATEGORY: [[]] AGREEABLE TIME	STANDARDS LABOR: 3.0 Hours	
LOCATION X SERVICE CENTER (RETURN TO FACTORY) CATEGORY:	SERVICE [[]] RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT	USED [[]] RETURN PARTS:[[]] SCRAP [[]] SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 18 April 2014	
X Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: WN AUTHOR: DYCS	
ADDITIONAL INFORMATION: UNIT MUST BE RETURNED TO FACTORY FOR REPAIR.		

© AGILENT TECHNOLOGIES, INC. 2013 PRINTED IN U.S.A.



April 12, 2013


Rev. 21

Page 2 of 2 N9918A-02

Situation:

FieldFox instruments with the serial numbers listed below may show potential DANL failures with 3-4 dB difference due to misloaded inductor on the RF board. If DANL improvement is necessary, a new RF board is available to fix this it.

Figure 1: Image showing the good and bad inductor on location U678 at RF Board



Solution/Action:

Affected FieldFox with necessary DANL improvement are required to send back to Agilent factory for a new RF board replacement. Test and Adjustment shall be done before shipping back to customer.

	Serial Numbers
1	SG52407002
2	MY52401215
3	MY52401203
4	MY52401218
5	MY52401204
6	MY52401210
7	MY52401195
8	MY52401209
9	MY52401192
10	MY52401205
11	MY52401208
12	MY52401201
13	MY52401222
14	MY52401194
15	MY52401211