

MODIFICATION RECOMMENDED

NCM346A-01A-RECALL

S E R V I C E N O T E

Supersedes: NCM346A-01-RECALL

NCM346A – NoiseCom Noise Source

Serial Numbers: T575

NFA Series Noise Figure Analyzer based noise source calibration systems calibrated by Agilent Technologies between May 1, 2009 and November 08, 2010, are not able to provide consistent Excessive Noise Ratio results when testing NoiseCom noise sources at frequencies ≤ 1 GHz.

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 1.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 01-JAN-2012	
AUTHOR:	MW	PRODUCT LINE: **	
ADDITIONAL INFORMATION: Gratis Support need to be chosen as the billing type, while creating the customer order.			

© AGILENT TECHNOLOGIES, INC. 2010
PRINTED IN U.S.A.

December 20, 2010

Rev. 17



Situation:

The Quality issue is caused by a different 28V noise source drive pulse supplied by the Noise Figure Analyzer series (N8973A, N8974A and N8975A) versus the 8970A/B, Noise Figure Meter. The NoiseCom noise sources calibrate fine on Agilent's 8970 series based calibration systems because of the much slower 28V pulse. The NFA series of analyzers has a much faster pulse, which generates a ~6 dB ENR delta at 10 MHz and ~1 dB ENR delta at 100 MHz test points on the NoiseCom noise sources. At these test points the ENR values will measure lower than expected.

Solution/Action:

1. Customer, please contact nearest Agilent Customer Care Center and send instrument to Agilent for free calibration.
2. Agilent WCSS Service & Support to send affected products to

Noisecom
25 Eastmans Road
Parisippany, NJ 07054
United States
Phone: +1 (973) 386-9696
Fax: +1 (973) 386-9191
Email: info@noisecom.com

for re-calibration at Agilent's expense.

3. After re-calibration Agilent to send the instrument back to the customer.