U1186A-01

Modification Recommended Service Note

Supersedes: NONE

U1186A Thermocouple (K-type) and Temperature Probe Adapter

Serial Numbers: ALL

The Problem – U1186A K-type thermocouple and temperature probe adapter set could have a faulty temperature probe adapter.

Parts Required:

P/N Description Qty. U1184-64101 Temperature Probe Adapter 1

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 0.25 Hours		
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) [X] SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [X] SCRAP [X] SEE TEXT [[]] SEE TEXT		
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 25 June 2021		
	[[]] Calibration Required [X] Calibration NOT Required	PRODUCT LINE: GM AUTHOR: WY		

ADDITIONAL INFORMATION:



Situation:

The U1186A K-type thermocouple and temperature probe adapter set purchased in Dec 2019 to May 2020 could have a faulty temperature probe adapter (U1184A).


A faulty temperature probe adapter will cause meter to show "OL" when the temperature probe adapter with a probe is plugged into the input jacks of a handheld meter.

Users will not be able to perform temperature measurement when using this faulty temperature probe adapter.

Solution/Action:

Perform the steps below to verify your temperature probe adapter:

- 1. Select temperature measurement on your handheld meter.
- 2. Insert the temperature probe adapter with a probe into the input jacks of the meter.



- 3. When a faulty temperature probe adapter is plugged in, your meter will show "OL" (open thermocouple).
- 4. Certain meters might not show "OL" when a faulty temperature probe adapter is plugged in. For this case, verify the temperature probe adapter with a known temperature.
- 5. If the temperature probe adapter is verified faulty, kindly contact Keysight Customer Contact Center at www.keysight.com/find/contactus to return the temperature probe adapter and get a new replacement part.

Revision History:

Date	Service Note Revision	Author	Reason for Change	
25 June 2020	01	WY	As Published	