

U2002A-03

S E R V I C E N O T E

Supersedes:
NONE

U2002A 50MHz – 24GHz USB Sensor

Serial Numbers: [0000A00000 / 9999Z99999]

Difficulty to attach USB power sensor cable to power sensor unit.

To Be Performed By: Customer

Parts Required:

P/N	Description	Qty.
U2000-60002	Cable, Main Assembly 1.5m	1
	OR	
U2000-60003	Cable, Main Assembly 3m	1
	OR	
U2000-60004	Cable, Main Assembly 5m	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	X IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 0.0 Hours
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP X SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP X SEE TEXT
AVAILABILITY:	ALWAYS	NO CHARGE AVAILABLE UNTIL: MARCH 2009	
AUTHOR: AB	PRODUCT LINE: WC		
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2008
PRINTED IN U.S.A.



Situation:

When the USB power sensor cable is attached to the power sensor unit, user may find it difficult to attach the cable to the power sensor unit.

Solution/Action:

If user faces difficulty to attach the cable to the power sensor unit, kindly contact Agilent for free of charge cable replacement. Kindly scrap the used cable.



Figure 1: USB power sensor cable fully attached to power sensor unit



Figure 2: USB power sensor cable not fully attached to power sensor unit