U8489A-01A

Modification Recommended Service Note

Supersedes: NONE

U8489A-Power Sensor; USB thermocouple, 1mm coaxial

Serial Numbers: US56430112 - US56430150

The Problem - U8489A Power Sensor was incorrectly calibrated

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

Service inventory and Used parts is Not Applicable

ACTION	[]] ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	[[X]] AGREEABLE TIME	LABOR: 2 Hours			
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) [[X]] SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: INVENTORY:	[[]] RETURN [[]] SCRAP [[X]] SEE TEXT	USED PARTS:	[[]] RETURN [[]] SCRAP [[X]] SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 11- May- 2021			
[[X]] Calibration Required [[]] Calibration NOT Required		PRODUCT LINE: WN AUTHOR: LSL			
ADDITIONAL	INFORMATION:				



Situation:

A situation has been uncovered where the U8489A Power Sensor was incorrectly calibrated due to an equipment malfunction. This caused the calibration error at 64 GHz. This would cause customers to make incorrect power measurements at this frequency.

Solution/Action:

- 1. Verify that your instrument(s) corresponds to the above model and serial numbers.
- 2. Please contact Keysight Technologies' Customer Contact Center, listed at www.keysight.com/find/contactus
- 3. Please arrange return of the U8489A Power Sensor to a Keysight Service Center to have this product recalibrated to eliminate this error.

Revision History:

Date	Service Note Revision	Author	Reason for Change
11 May 2018	01	LSL	As Published
18 July 2018	02	LSL	Change on the Action Category to Agreeable Time