U8903A-01 S ERVICE

> Supersedes: NONE

U8903A Audio Analyzer

Serial Numbers: MY49000000 - MY50439999

EMI shield soldering improvement

Parts Required:

Description P/N Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY::	AGREEABLE TIME	[[]] PERFORMANCE ENHANCEMENT [X] SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE [X] SERVICE CENTER [[]] CHANNEL PARTNERS	AVAILABILITY: 30 June 2012
AUTHOR: TY		PRODUCT LINE: WC
ADDITIONAL INFORMATION: Not Applicable		

© AGILENT TECHNOLOGIES, INC. 2011 PRINTED IN U.S.A.

Agilent Technologies

Page 1 of 2

March 29, 2011

Rev. 18

Page 2 of 2 U8903A-01

Situation:

Improve the EMI shield plate soldering quality.

Solution/Action:

Please identify the symptom before proceed. Picture shown below applied for both cases.

1. Situation 1 – EMI shield plate loose and moveable

Estimated rework time: 30 minutes

Tools required: As stated in service guide and soldering tool

i. Follow the service guide to remove the top cover of U8903A.

- ii. Check if EMI shield plate is loose or moveable.
- iii. Apply solder to the soldering pad (location as shown at red square box).
- iv. Clean the surrounding soldering area to avoid any solder shorts.

2. <u>Situation 2 – EMI shield plate fallout from PCBA</u>

Estimated rework and cal setup time: 90 minutes Estimated testing time: 4 hours (no hands on)

Tools required: As stated in service guide and soldering tool

- i. Follow the service guide to remove the board.
- ii. Apply solder to the thru holes and soldering pad.
- iii. Clean the surrounding soldering area to avoid any solder shorts.
- iv. Perform calibration.

