1158A-02

Modification Recommended Service Note

Supersedes:

NONE

1158A Active Probe, 4 GHz

Serial Numbers: ALL

This product 1158A was scheduled to go End of Support in Sept 2019, but to circumstances that were out of Keysight Technologies control we were forced to End Service life prematurely.

Parts Required:

P/N Description Qty.

01158-68701 1 is now EOS and see below for replacement details

ADMINISTRATIVE INFORMATION

| ACTION CATEGORY: | X ON SPECIFIED FAILURE [[]] AGREEABLE TIME | STANDARDS LABOR: 0.5 Hours | |
|------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|--|
| LOCATION CATEGORY: | [[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) X SERVICE CENTER [[]] CHANNEL PARTNERS | SERVICE: [[]] RETURN USED X RETURN INVENTORY: [[]] SCRAP X SEE TEXT PARTS: [[]] SCRAP [[]] SEE TEXT | |
| AVAILABILITY: PRODUCT'S SUPPORT LIFE for units in warranty | | NO CHARGE AVAILABLE UNTIL: Feb. 11, 2018 | |
| [[]] Calibration Required X Calibration NOT Required | | PRODUCT LINE: [1A] AUTHOR: MR | |

ADDITIONAL INFORMATION:



Situation:

- This product 1158A was scheduled to go End of Support in Sept 2016, but to circumstances that were out of Keysight Technologies control we were forced to End Service life prematurely. For support parts 1158A - 01158-68701 those parts are not available any longer and we are forced to support products in warranty or with existing extended warranties until at the time those run out

Solution/Action:

Please recommend the N2752A-FG for the support part.

Here are the recommendations to customers and questions to ask them how to best fit a replacement probe to fill this warranty requirement. Note that the replacement probe may not support the scope that the 1158A was used with, so ensure the scope compatibility listed below in the table before recommending the replacement probe.

| | 1158A 4GHz |
|----------------------|--------------------------------------------------------------------------------------------------------|
| Replacement option 1 | N2752A 6 GHz |
| Scope compatibility | InfiniiVision 3000X/T,4000X, 6000, and Infiniium 9000, S, 90000A |
| Disclaimer | Not supporting legacy InfiniiVision 5000/6000/7000 and Infiniium 548xx, 8000, 80000 Series |
| | |
| Replacement option 2 | 1132A 5GHz with E2676A SE browser or/and E2679A SE solder-in head |
| Scope compatibility | All InfiniiVision 3000X/T, 4000X, 6000X, 5000, 6000, 7000 and all Infiniium models |
| Disclaimer | Limited probe tip accessories offered with InfiniiMax |
| | |

| Replacement option 3 | |
|----------------------|--|
| Scope compatibility | |
| Disclaimer | |

Contact CSG_Support@keysight.com if there is a scope compatibility issue and we can see case by case what steps to take next.

Revision History:

| Date | Service Note Revision | Author | Reason for Change | |
|--------------|-----------------------------|-------------|-------------------|--|
| 06-June-2016 | 01 | Mark Rowley | As Published | |
| | | | | |