

S E R V I C E N O T E

SUPERSEDES: 18281A-01A

18281A ISDN Basic Rate Monitor and Simulate Interface

18281-66513 PCBA-Processor

Serial Numbers: 0000A00000 / 9999A99999**Country Specific Firmware Available****Situation:**

Customers may require country specific firmware for their 18281A ISDN pod. The following ROMs are available:

Standard (USA)	18281-19016	ROM-Lo
	18281-19017	ROM-Hi
British	18281-19018	ROM-Lo
	18281-19019	ROM-Hi
French	18281-19030	ROM-Lo
	18281-19031	ROM-Hi
German	18281-19022	ROM-Lo
	18281-19023	ROM-Hi
Swiss	18281-19028	ROM-Lo
	18281-19029	ROM-Hi
Sweden	18281-19026	ROM-Lo
	18281-19027	ROM-Hi

Continued

DATE: 16 November 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

NB

3800

Caution: ESD Protection required (work at static safe workstation)

- | | | | |
|------------------------------|-----|----|-----------|
| ROM | ROM | ++ | |
| Lo | Hi | ++ | |
| | | ++ | |
| | | ++ | |
| | | ++ | |
| oooooooooooooooooooooooooooo | | ++ | Connector |
| oooooooooooooooooooooooooooo | | ++ | |

5. Remove ROM-Lo, and replace with appropriate ROM-Lo. Remove ROM-Hi, and replace with appropriate ROM-Hi.
6. Reinstall top board and hardware.
7. Reinstall top cover and hardware.