INFORMATION ONLY

33612A-02

S E R V I C E N O T E

Supersedes: NONE

33612A Waveform Generator

Serial Numbers: ALL

Firmware on this instrument should be updated to the latest revision before any repairs are initiated on this product.

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
[[]] Calibration Required	PRODUCT LINE: GM	
X Calibration NOT Required	AUTHOR: MDB	
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2014 PRINTED IN U.S.A.



April 7, 2014

Page 2 of 2 33612A-02

Situation:

False error messages at power-on were generated with previous versions of the firmware.

Solution/Action:

The firmware in the 33612A should be updated to the latest version before proceeding with repairs. This will avoid false error messages at power-on. Go to www.agilent.com/find/33612A to find the latest revision of the firmware.

Revision History:

Revision Number	Date	Author	Reason For Change
1.0	4-04-2014	MDB	As published