# INFORMATION ONLY

# <u>33621A-02</u> <u>S E R V I C E N O T E</u>

Supersedes: NONE

## 33621A Waveform Generator

Serial Numbers: ALL

Firmware on this instrument should be updated to the latest revision before any repairs are initiated on this product.

Parts Required: P/N Description


Qty.

NONE

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
INFORMATION ONLY			
[[]] Calibration Required	PRODUCT LINE: GM		
X Calibration NOT Required	AUTHOR: MDB		
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2014 PRINTED IN U.S.A.





## Situation:

False error messages at power-on were generated with previous versions of the firmware.

## Solution/Action:

The firmware in the 33621A should be updated to the latest version before proceeding with repairs. This will avoid false error messages at power-on. Go to <a href="https://www.agilent.com/find/33621A">www.agilent.com/find/33621A</a> to find the latest revision of the firmware.

#### **Revision History:**

Revision Number	Date	Author	Reason For Change
1.0	4-04-2014	MDB	As published