

S E R V I C E N O T E

SUPERSEDES: None

3455A Digital Multimeter**Serial Numbers:** 0000A00000 / 9999A99999**Fan Replacement Kit available for defective cooling fan****Duplicate Service Notes:**

3437A-10

3455A-30

To Be Performed By: Agilent-Qualified Personnel**Parts Required:**

Part No.	Description
03455-89801	Replacement Fan Kit

Situation:

The part number 3160-0266 has been discontinued by the part manufacturer. Effective immediately for the 3455A (& 3437A) , a new kit, P/N 03455-89801, will be used in its place.

Continued

DATE: June 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

RM

0940

Solution/Action:

If the fan, “B1”, fails, replace with new replacement fan kit (P/N 03455-89801). Some modification is required (see Replacement Fan Installation Note included in the kit).

Kit Contents:

- Replacement Fan W/Lugs
- Mounting and Support Hardware
- Replacement Fan Installation Note