

34902A -05

S E R V I C E N O T E

Supersedes:
NONE

34902A 16-Channel Reed Multiplexer Module

Serial Numbers: ALL US, MY, SG

New Relay Verification Procedures: 34901A, 34902A, 34904A, 34908A Modules

Parts Required:
NONE

Situation:

The relay verification procedures have been redesigned for the 34901A, 34902A, 34904A and 34908A. The new procedures use an external DMM to make 4 wire resistance measurements across various paths containing relay contacts. The procedure allows you to identify bad relays. It is more complete compared to the old procedure.

Solution/Action:

The new procedures can be found in Edition 3 of the 34970A Service Guide. The 34970A Service Guide can be obtained by:

- 1) Downloading/Viewing Service Guide via the web – Go to www.agilent.com/find/34970A scroll to the bottom of the page and select link “Manuals, Guides and Notifications”
- 2) Ordering the 34970A manual set, part number 34970-90101.

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DAA PRODUCT LINE: 9E

ADDITIONAL INFORMATION: