0.40004.00

# Information Only Service Note

Supersedes: NONE

# 34923A 40/80 Channel Reed Multiplexer for 34980A

Serial Numbers: ALL

The Problem - New Keysight Color

# Parts Required:

P/N Description Qty. 34923-60001 40/80-Channel Reed Multiplexer new replacement unit 1 34923-66001 Reed Multiplexer,40/80-Channel new replacement unit (Rebranded) 1

## ADMINISTRATIVE INFORMATION

[[]] Calibration Required PRODUCT LINE: PLGM
[X] Calibration NOT Required AUTHOR: SL

ADDITIONAL INFORMATION:



#### Situation:

The outlook of the instrument is experiencing a color change to comply with the new Keysight product color scheme. The redesigned 34923A provides the same product performance, specifications, and is 100% compatible with the existing 34923A.

### Solution/Action:

# Keysight customers:

No action is needed.

# Keysight service centers:

For new unit replacement below MY56481099, use the part number 34923-60001 (Reed Multiplexer, 40/80-Channel). These parts are available as UTG. Once the parts are depleted, use the rebranded part numbers 34923-66001 (Reed Multiplexer, 40/80-Channel rebranded).

For new unit replacement of MY56481099 and above, use directly the rebranded part numbers 34923-66001 (Reed Multiplexer, 40/80-Channel rebranded).

# **Revision History:**

Date	Service Note Revision	Author	Reason for Change	
13 Feb 2020	01	SL	As Published	