					3497	0A-02	2B
S E F	R V	I C	Е	Ν	0	Т	Ε
34970A Data	Acquisition	/Switch		UPERSEDE	S: 3497	0A-02A	
Serial Numbers:	0000A00000 /	US3700932	29				
failures; See SN 34970 To Be Performed			·				
Parts Required: Model	P/N	D	escription	Quantity			
34970A Std 34970A, Opt. 001	34970-692	01 Rep	lacement Unit lacement Unit	1			
						Continuec	đ
			D	ATE: Nove	mber 200)1	

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:							
MODIFICATION RECOMMENDED							
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: LABOR 0.5 Hours					
LOCATION CATEGORY:	 CUSTOMER INSTALLABLE ON-SITE SERVICE CENTER 	SERVICE RETURN USED RETURN INVENTORY: SCRAP SCRAP SCRAP SEE TEXT SEE TEXT SEE TEXT					
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL:					
AUTHOR: DAA	ENTITY: 0940	ADDITIONAL INFORMATION:					

© 2001 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.



Situation:

The instrument fails to power on when connected to an ac power line. This condition is most likely to occur when the unit was unplugged for a short period of time or following a brief power outage.

NOTE

This issue may appear to be a "no trouble found" in the service office. Units that have been disconnected from the line may not show this problem again for several weeks.

Solution / Action:

Defective units should be exchanged for a replacement unit (Choose appropriate part number listed above).