

34980A-02

S E R V I C E N O T E

Supersedes:
NONE

34980A Multifunction Switch/Measurement Unit

Serial Numbers: MY00000000 - MY44006427

Plug-in modules purchased after June 1, 2008 require 34980A mainframe firmware revision 2.33 or greater.

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

Situation:

34980A plug-in modules purchased after June 1, 2008 has new microprocessor that needs mainframe firmware version 2.33 or greater in order to work.

Solution/Action:

Update the 34980A Mainframe Firmware to 2.33 or greater:

1. Go to the Agilent 34980A Firmware Update Page at <http://www.agilent.com/find/34980Aupdates>.
2. On this page, locate the section 'Procedure to install 34980A Firmware Revision 2.33 (or greater)'. Download and install the Firmware Update Utility on your PC as directed.
3. Once the utility is installed, continue with installation of the mainframe firmware.

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: TP	PRODUCT LINE: SP
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2008
PRINTED IN U.S.A.

June 16, 2008

Rev. 14

