# S E R V I C E N O T E

3499A Switch/Control Mai	SUPERSEDES: 3499A-03A	
<b>Serial Numbers:</b> Products with Firmware 1.0/1.1 and within the Below Serial Number.		
cn38428201/40050719 and except th	ne following Serial Numbers:	
38428249	40050312	
38428398	40050319	
38428448	40050328	
38428455	40050332	
38428456	40050341	
38428458	40050395	
38428461	40050396	
38428463	40050397	
38428467	40050398	
38428469	40050400	
38428471	40050401	
38428472	40050404	
38428473	40050405	
38428622	40050408	
40050154	40050409	
40050260	40050463	
40050264	40050466	
40050267	40050467	
40050287	40050582	
40050310		
40050311		
	Continu	
	DATE: April 2001	

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	<ul><li>■ IMMEDIATELY</li><li>☐ ON SPECIFIED FAILURE</li><li>☐ AGREEABLE TIME</li></ul>	STANDARDS: LABOR 0.5 Hours
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE □ ON-SITE □ SERVICE CENTER	SERVICE ☐ RETURN USED ☐ RETURN PARTS: ☐ SCRAP SEE TEXT ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: April 2003
AUTHOR: AJT	ENTITY: Y500	ADDITIONAL INFORMATION:

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



# No display(dark) or blinking after power switch on. Defect in the battery back-up circuit.

To Be Performed By: Agilent-qualified personell

### Parts Required:

HP P/N Description Quantity
03499-69001 3499A Mainframe 1

#### **Situation:**

In normal 3499A working environment, the 3499A have experienced a lockupproblem. The display show up a blinking or dark and no response from key or buttons and the instrument is stop working. Some failure unit also showed a defect in the battery back-up circuit.

#### **Solution / Action:**

We would like to exchange customer's unit for one that has been upgraded/modified to eliminate this potential failure.