S C Ε R E V N SUPERSEDES: NONE 3764A Digital Transmission Analyzer **Serial Numbers:** 2322U00101 / 9999U99999 **Situation:** On some 3764A Option 003 instruments, connectors J1 and J3 on 03764-60176 Assembly may have been wrongly marked (Figure 1). This would result in the signals from DATA O/P 1 and DATA O/P 3 being crossed. Figure 2 shows correctly marked boards. J3 J2 J1 DATA 1 DATA 2 DATA 3 Figure 1. Wrongly Marked Board J3 J2 J1 DATA 3 DATA 2 DATA 1 Figure 2. Correctly Marked Board

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
JH	1400	

© 1991 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Continued

DATE: 1 June 1991

Solution/Action:

Ensure that the rear panel DATA O/P 1 is connected to J1 and DATA O/P 3 is connected to J3 on the 03764-60176 Assembly.