

S E R V I C E N O T E

SUPERSEDES: None

4062UX Semiconductor Process Control System

Duplicate Service Notes: 4062C-05

Serial Numbers: 2848J00142 / 2848J00150

Repair a breaker in the system cabinet

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N	Qty	Description
3105-0238	1	Breaker

Situation:

A 4062UX with one of the above serial numbers may have been shipped with an incorrect breaker in its cabinet. This may damage system components.

Normally a 30 A max. breaker is installed in the 4062UX system cabinet. Through an oversight at the factory, a 3 A max. breaker was shipped in some of the 4062UXs instead.

Solution/Action:

Change the breaker to the correct one. The P/N for the correct breaker is 3105-0238.

Continued

DATE: 30 August 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	<input checked="" type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 hrs		
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	RESPONSIBLE ENTITY: 3300	UNTIL: Aug '93		
AUTHOR: IT	ENTITY: 3301	ADDITIONAL INFORMATION:			



This is just a precautionary measure because before this service note was published, all incorrect breakers in 4062UXs with the above serial numbers were changed. Therefore, future action is probably not required.