4263B-02

S	Е	R	V	Ι	С	Е	Ν	0	Т	Е	
426	3B LC	R Met	er				SUPERSED	ES: NON	E		
Seria	al Numb	ers: 4263	B: JP1K	D02861	/ JP1KE	003668					
Modification to prevent "ADC FAILURE" after power on / Reset is done											
To Be Performed By: Agilent-Qualified Personnel											
Parts Required:											
P/N		Desc	ription			Qı	antity				
0426	53-85071	4263	B ROM	Rev.01.	.04		1				
Situ	ation:										
The 4263B specified above may incorrectly indicate "ADC FAILURE" after the 4263B is turned on or its "Reset" function is done.											
Solution / Action:											
Replace the ROM to revision 01.04.											
							DATE: Sep	tember 19	98		
							2,112. 000				

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: MODIFICATION RECOMMENDED								
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: LABOR 0.5 Hours						
LOCATION CATEGORY:	 ☐ CUSTOMER INSTALLABLE ☐ ON-SITE ■ SERVICE CENTER 	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT SEE TEXT						
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: September 2000						
AUTHOR: KW	ENTITY: 3355	ADDITIONAL INFORMATION: None						

© 1998 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

