S E R V I C E N O T E

SUPERSEDES: None

HP 4332A LCR METER

Serial Numbers: 0000J00000 / 1848J02935

Duplicate Service Notes: None

Repair method for defective IC amplifier

To Be Performed By: HP-qualified personnel

Parts Required:

HP P/N Qty. Description

04332-7721 1 OSCILLATOR PC BOARD ASS'Y

Situation:

When the IC amplifier PN 1820-0051 has to be replaced, it is necessary to replace the whole board with a re-designed board, because the PN 1820-0051 cannot be purchased any longer.

Continued

DATE 14 October 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICAT	TION:			
INFORMATION ONLY				
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:		
YO	3355			

© 1991 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



Page 2 Service Note 4332A-02

Solution/Action:

When any of following parts has to be replaced:

Reference Designator	HP Part No.	Description
A1IC1	1820-0051	IC:AMP DC HI GAIN
A1IC4	1820-0051	IC:AMP DC HI GAIN
A1IC5	1820-0051	IC:AMP DC HI GAIN

Order the following part and replace the whole board:

HP Part No. Description

04332-7721 OSCILLATOR PC BOARD ASS'Y