# S E R V I C E N O T E

SUPERSEDES: None

## **HP 4332A LCR Meter**

**Serial Numbers:** 0000J00000 / 1848J02940

**Duplicate Service Notes:** None

### Repair method for defective IC amplifier

To Be Performed By: HP-Qualified Personnel

Parts Required:

HP P/N Qty. Description

04332-7724 1 HEAD AMP PC BOARD ASS'Y

Situation:

When the IC amplifier PN 1820-0051 has to be replaced, it is necessary to replace the whole board with a re-designed board, because the PN 1820-0051 cannot be purchased any longer.

Continued

DATE: 14 October 1991

#### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICAT	FION:	
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
YO	3355	

© 1991 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



Page 2 Service Note 4332A-03

### Solution/Action:

When any of following parts has to be replaced:

Reference Designator HP Part Number Description

A4IC1 1820-0051 IC:WIDEBAND DC AMP

order the following part and replace the whole board:

HP Part No. Description

04332-7724 HEAD AMP PC BOARD ASS'Y