

S E R V I C E N O T E

SUPERSEDES: NONE

4352B VCO/PLL Signal Analyzer**Serial Numbers:** JP1KE00000 / JP1KE00195**No display when power is on.****Duplicate Service Notes:**

4291B-06

4395A-07

4396B-08

To Be Performed By: Agilent-Qualified Personnel**Parts Required:**

P/N	Description	Quantity
0950-3246	A40 Per-Regulator	1

Situation:

The A40 Pre-Regulator does not perform to published specifications. The LCD display malfunctions. Also, the fan does not run when the 4352B is turned on. This is Power Supply Sequence shutdown problem.

Solution / Action:

Check the A40 Pre-regulator of Power Supply Troubleshooting using the Service Manual. Defective A40 pre-regulator should be replaced with a new A40 pre-regulator.

DATE: July 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☒ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ SERVICE CENTER	SERVICE INVENTORY: ☐ RETURN ☐ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☐ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: July 2001
AUTHOR: KW	ENTITY: 3355	ADDITIONAL INFORMATION:	

