

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

4395A-17

S E R V I C E N O T E

Supersedes:
[NONE]

Agilent 4395A Network/Spectrum/Impedance Analyzer

Serial Numbers: 0000A00000/9999Z99999

Upgrade firmware to revision 1.10 when exchanging A8 board of 4395A that has firmware revision below 1.10.

Parts Required:

P/N	Description	Qty.
5182-7513	FW revision label 1.10	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: HM PRODUCT LINE: WN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2005
PRINTED IN U.S.A.



July 5, 2005

Situation:

The combination of firmware below revision 1.10 and A8 board may cause occasional rise in noise floor and occasional shift of measurement signal in frequency with SA mode.

Solution/Action:

Download firmware revision 1.10 at below URL and order 5182-7513. Follow firmware installation procedure described in the service manual to upgrade firmware.

http://kobemktg.jp/agilent.com/field_eng/service/firmware_history/fwhist_4395a.htm