S E R V I C E N O T E

SUPERSEDES: NONE

4396A Network/Spectrum Analyzer

Serial Numbers: 0000J00000 / 9999J9999

Option Upgrade Procedure

Duplicate Service Notes: None

Parts Required: See text.

Solution/Action:

4396U upgrade kit listed below is available for retrofitting options into the analyzer. Each option code is corresponding to an analyzer's option retrofitted.

Upgrade Kit	Customer Installable?	Estimated Labor	Remark
4396U Opt 010	Yes	.5 Hour	See Note1, Note2
4396U Opt 1C2	No	1 Hour	See Note1
4396U Opt 1D5	No	1 Hour	
4396U Opt 1D6	No	1 Hour	See Note1
4396U Opt 1D7	Yes	Not Applicable	
4396U Opt 00M	No	1 Hour	

Continued

DATE: 01 March 1994

ADMINISTRATIVE INFORMATION

	SERVICE NOTE CLASSIFICATION:					
	INFORMATION ONLY					
	ADDITIONAL INFORMATION:	ENTITY:	AUTHOR:			
		3355	AY			
-	1	ENTITY:				

© 1994 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Note1: Must specify the serial number of the 4396A when ordering the upgrade kit.

Note2: 4396A firmware revision 3.00 or more is required. To upgrade the firmware, see service note 4396A-01 and 4396A-04.

The upgrade kits to do not include the installation labor. The labor in the above table includes administrative time.