S E R V I C E N O T E

SUPERSEDES: None

4934A Transmission Impairment Measuring Set

Serial Numbers: 0000U00000 / 9999U99999



Short Circuit Hazard

Unavailability of Clam Shell, Part Number 03772-60015

To Be Performed By: Agilent-Qualified Personnel

Situation:

Clam shell, part number 03772-60015 is now unavailable.

Solution/Action:

The metalised clam shell, part number 03772-60025 may be used instead, providing that a strip of insulating tape is applied to cover the exposed PCB tracks on the front pane. Tape should run from the measurement frequency LED along to the existing tape. This avoids the short circuit hazard that would occur if the insulation process was not carried out.

DATE: September 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
SAFETY		
ACTION CATEGORY:	■ ON SPECIFIED FAILURE □ AGREEABLE TIME	STANDARDS: LABOR 0.5 HOURS
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE □ ON-SITE □ SERVICE CENTER	SERVICE
AVAILABILITY:	ALWAYS	AGILENT RESPONSIBLE UNTIL: ALWAYS
AUTHOR: GS	ENTITY:E600	ADDITIONAL INFORMATION:

© 1997 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

