

5065A-06

S E R V I C E N O T E

SUPERSEDES: None

5065A Rubidium Vapor Frequency Standard

Serial Numbers: 0000A00000/9999Z99999

C1 on Main Chassis Assembly (0180-0056)

Replacement of Obsolete Electrolytic Filter Capacitor

Duplicate Service Notes: 5087A-12

To be Performed by: HP-Qualified Personnel or Customer

Parts Required: 5063-2341 Capacitor and 05065-9051 Installation Note

Situation:

Part number 0180-0056 has been obsoleted and can no longer be supplied. A replacement assembly 5063-2341 has been developed to replace 0180-0056 with minor modification.

Solution:

When it has been determined that C1 has failed and 0180-0056 is not available, 5063-2341 can be installed in its place by enlarging one of the four mounting slits to accept a 6-32 screw and washer. Step-by-step instructions are listed, if necessary, in Installation Note 05065-9051.

DATE: June 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

CF

ENTITY:

0200

ADDITIONAL INFORMATION:

© 1996 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

